



**VTO V4.510.0000002.1.R.220613**

**Release Notes**



# Legal Information

## Copyright

© 2022 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to as "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

## Trademarks

, , , and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

## Disclaimer

- These release notes are for reference only. Slight differences might be found between the release notes and the product.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, we reserve the right of final explanation.

---

# Table of Contents

<b>Legal Information .....</b>	<b>I</b>
<b>Release Notes .....</b>	<b>1</b>
1.1 Overview .....	1
1.2 New Features.....	1
1.3 Fixed Bugs .....	1
1.4 Compatibility.....	1
1.4.1 Program .....	1
1.4.2 Browser.....	1
1.4.3 Third Party Access.....	1
1.5 Software Environment.....	2
1.6 Pending Issues.....	2
1.7 Update Guide .....	2

# Release Notes

## 1.1 Overview

Item	Description
Product model	Villa Door Station
Version	V4.510.0000002.1
Software package information	DH_VTOXXXEFQR_MultiLang_PN_128M_SIP_V4.510.0000002.1.R.20613.zip
OS requirement	None
Release date	June 17, 2022

## 1.2 New Features

None.

## 1.3 Fixed Bugs

Fixed Bug	Description
1	Fixed the bugs that threaten the security of the program.
2	PaaS service might be automatically disabled.

## 1.4 Compatibility

### 1.4.1 Program

DH\_VTOXXXEFQR\_MultiLang\_PN\_128M\_SIP\_V4.510.0000002.1.R.220613.zip

### 1.4.2 Browser

None.

### 1.4.3 Third Party Access

None.

## 1.5 Software Environment

Category	Model	Version
Indoor Monitor	DHI-VTH2421FB-P	DH_VTHX421H_MultiLang_SIP_V4.500.0000002.0.R.210713
	DHI-VTS5340B	DH_VTS5340B_MultiLang_NP_SIP_V4.500.0000001.0.R.210714
	DHI-VTH5421HW	DH_VTH542XH_MultiLang_SIP_V4.500.0000002.0.R.210715
	DHI-VTH1550CH-S2	DH_VTHX421L_MultiLang_SIP_V4.500.0000001.0.R.210714
	DHI-VTH2621G-WP	DH_VTHX6XXX-SX_MultiLang_SIP_V4.510.0000000.0.R.211210
	DHI-5422HW	DH_VTHX6XXX-SX_MultiLang_SIP_V4.510.0000000.0.R.210804.zip
Client	DMSS	IOS: DMSS V1.9.6.002 20211213204800
Tool	ConfigTool	V5.000.0000001.8.R
Platform	DSS Pro	General_DSS-Professional_Win64_IS_V8.000.0000003.0.R.20210729

## 1.6 Pending Issues

No.	Issue Description	Possible Result	How to Fix
1	When the indoor monitor monitors the second confirmation station, the lock 2 icon on the screen of the indoor monitor is highlighted.	No response after tapping the lock icon.	Hide the lock 2 icon.

## 1.7 Update Guide

Refer to the update guide.

**ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.**

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: [overseas@dahuatech.com](mailto:overseas@dahuatech.com)

Website: [www.dahuasecurity.com](http://www.dahuasecurity.com)