



Network Video Recorder

V4.002.0000001.2.R.221207

Release Notes



Legal Information

Copyright

© 2021 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to as "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

 ,  ,  , and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only. Slight differences might be found between the release notes and the product.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, we reserve the right of final explanation.

Table of Contents

| | |
|---|----------|
| Legal Information | I |
| Release Notes | 1 |
| 1.1 Overview | 1 |
| 1.2 Product Introduction | 1 |
| 1.3 New Features | 2 |
| 1.4 Fixed Bugs | 2 |
| 1.5 Instructions for New Features | 2 |
| 1.6 Compatibility | 2 |
| 1.7 Software Environment | 2 |
| 1.8 Pending Issues | 3 |
| 1.9 Update Guide | 4 |

Release Notes

1.1 Overview

| Item | Description |
|------------------------------|---|
| Product name | Network Video Recorder |
| Version | V4.002.0000001.2 |
| Software package information | DH_NVR2XXX-I2_Mul_V4.002.0000001.2.R.221207.zip |
| Model | DHI-NVR2104-I2 DHI-NVR2108-I2 DHI-NVR2116-I2 DHI-NVR2104-P-I2 DHI-NVR2108-8P-I2 DHI-NVR2104HS-I2 DHI-NVR2108HS-I2 DHI-NVR2116HS-I2 DHI-NVR2104HS-P-I2 DHI-NVR2108HS-8P-I2 DHI-NVR2204-I2 DHI-NVR2208-I2 DHI-NVR2216-I2 DHI-NVR2204-P-I2 DHI-NVR2208-8P-I2 DHI-NVR2216-16P-I2 |
| Onvif Version | V2.4.1 |
| OS requirement | None |
| Release date | Dev 07, 2022 |

1.2 Product Introduction

This product is mainly used indoors. Combined with IP cameras, you can use this NVR to complete real-time monitoring and recording. It supports configuring basic parameters by using mouse, and you can build a security monitoring network through web or other professional software developed by Dahua. It supports real-time monitoring, record playback, alarm, and other auxiliary configuration functions.

1.3 New Features

| Feature | Description |
|---------|-------------|
| None. | None. |

1.4 Fixed Bugs

None.

1.5 Instructions for New Features

This version fixes some bugs, It does not update the functions. For instructions on product functions, refer to previously published materials.

1.6 Compatibility

After updating to the new baseline version from previous baseline (V4.002.0000001.2.R.221123), users cannot roll back to versions of previous baseline.

1.7 Software Environment

| Device Model | Software Version |
|------------------------------------|---|
| DH-IPC-HFW1230SP-0280 B-S5-QH2 | DH_IPC-HX1XXX-Edison2_EngSpnRus_PN_V2.800.0000000 .5.R.210929.zip |
| DH-IPC-HFW1330SP-0280 B-S5 | DH_IPC-HX2(1)XXX-Molec_EngSpnRus_PN_V2.800.000000 0.16.R.211026.zip |
| DH-IPC-HFW1530SP-0280 B-S6 | DH_IPC-HX1XXX-Hertz_EngSpnRus_PN_V2.800.0000000.1 6.R.211026.zip |
| DH-IPC-HFW1830SP-0280 B-S6 | DH_IPC-HX18XX-Molec_EngSpnRus_PN_V2.800.0000000.1 6.R.211026.zip |
| DH-IPC-HFW2231SP-S-028 0B-S2-QH | DH_IPC-HX2XXX-Taylor_MultiLang_PN_V2.840.0000000.2.R .211231.zip |
| DH-IPC-HDW2431TP-AS-0 280B-S2 | DH_IPC-HX2XXX-Molec_MultiLang_PN_V2.820.0000000.37. R.210901.zip |
| DH-IPC-HFW2831TP-ZAS- 27135-S2 | DH_IPC-HX25(8)XX-Molec_MultiLang_PN_V2.820.0000000.3 6.R.210723.zip |
| DH-IPC-HDW3241TP-ZAS- 27135 | DH_IPC-HX3XXX-Leo_MultiLang_PN_Stream3_V2.800.0000 000.37.R.220118.zip |
| DH-IPC-HFW3441TP-ZS-27 135 | DH_IPC-HX5(4)(3)XXX-Leo_MultiLang_PN_Stream3_V2.800. 0000000.37.R.220118.zip |
| DH-IPC-HDW1230C-A-V2 | DH_IPC-HX2(1)XXX-Edison_Chn_PN_V2.680.0000000.18.R. 201214.zip |

| | |
|---------------------------------|--|
| DH-IPC-HFW2233M-I2 | DH_IPC-HX3(2)XXX-Ohm2_Chn_PN_V2.820.0000000.6.R.220106.zip |
| DH-IPC-HDW2135C-A | DH_IPC-HX2(1)XXX-Leto_Chn_PN_V2.680.0000000.2.R.190301.zip |
| DH-IPC-HFW4433M-I2 | DH_IPC-HX5(4)(3)XXX-Leo_Chn_PN_Stream3_V2.800.0000000.37.R.220118.zip |
| DH-IPC-HDW3549HP-AS-PV-0360B-S3 | DH_IPC-HX5XXX-Volt_MultiLang_PN_Stream3_V2.840.0000000.13.R.220110.zip |
| DH-IPC-HFW2233M-AS-I1 | DH_IPC-HX3(2)XXX-Ohm_Chn_PN_V2.800.0000000.21.R.211126.zip |
| DH-IPC-HFW3433F-VFAS | DH_IPC-HX2XXX-Molec_Chn_PN_V2.820.0000000.37.R.210901.zip |
| DH-IPC-HFW3441EP-AS-0280B-S2 | DH_IPC-HX3XXX-Taurus_MultiLang_PN_Stream3_V3.000.0000000.8.R.220429.zip |
| DH-IPC-HDW3541TP-ZS-27135-S2 | DH_IPC-HX3XXX-Taurus_MultiLang_PN_Stream3_V3.000.0000000.8.R.220429.zip |
| DH-SD6C82FB-GN | DH_SD-Eos-Civil_Chn_PN_Stream3_V2.813.0000008.0.R.211014.zip |
| DH-SD49225XA-HNR | DH_SD-Prometheus_MultiLang_PN_Stream3_V2.812.0000000.5.4.R.210902.zip |
| DH-VTO7541G-V1 | DH_VTO75X95X_Chn_PN_SIP_V4.511.0000000.0.R.220119.zip |
| DHI-VTO6541H | General_VTO6531H-MCU_V1.001.0000000.0.R.210908.zip DH_VTO65XXX_Eng_PN_SIP_V4.511.0000000.0.R.211106.zip |
| DHI-VTO2211G-P | DH_VTOXXXXD-G_MultiLang_PN_PAAS_SIP_V4.511.0000000.0.R.211116.zip |
| DHI-VTO6521F | General_VTO6531H-MCU_V1.001.0000000.0.R.210908.zip DH_VTO65XXX_Eng_PN_SIP_V4.511.0000000.0.R.211106.zip |
| playsdk | General_PlaySDK_Chn_Windows64_IS_V3.044.0000002.1.R.210907.zip |
| COS PRO | V1.011.0000001 2022-03-15 |
| Player | V4.1.0.3 |
| ConfigTool | V5.0.1.8 |
| NetSDK | General_NetSDK_Chn_Win64_IS_V3.055.0000001.0.R.211101.7z |
| DiskManager | V1.0.0.1 |
| NKB1000-E | General_NKB1000_Eng_V3.621.0000000.0.R.200302.zip |

1.8 Pending Issues

None.

1.9 Update Guide

- You can upgrade the NVR by ConfigTool, web and USB flash drive. For details, see Upgrade Guide.
- Services such as recording and live view will be paused during the upgrade process. The NVR works normally after upgrade and rebooting.
- The upgrade does not affect previous settings of the NVR.
- Do not power off during the upgrade process, or the NVR will not boot up properly.

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: overseas@dahuatech.com

Website: www.dahuasecurity.com